front side board thickness 0.031" all 0.070" pads have 0.050" plated through holes on 0.100" grid

print 1:1 to fit check components lines between adapters grooved for easy snap-apart by hand




| Bellin Dynamic Systems Inc<br>3365 E Miraloma #208, Anaheim California 92806 | | | |
|---|---|---|---|
| Tolerances:<br>.XX = +/- .03"<br>.XXX = +/- .010" | Size<br>A | Title<br>Board, ChipChanger 40 | |
| Drawn: P Bellin | Part #: 526 | | Part Rev: None |
| Check: P Bellin | Doc #: 20176.PCB | | Sheet 1 Of 1 |